

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022306**Date Inspected:** 23-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Xu Le Feng**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

BAY#10

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 08603

Magnetic Particle Testing (MT)

This QA inspector performed MT of the area previously tested and accepted by ZPMC Quality Control personnel.

This QA Inspector generated an MT report for this date. The member is identified as OBG Component. The weld designation reviewed as follows:

BIKE PATH

BK17-001-041; 047; 048; 053; 055

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 08606

Ultrasonic Testing (UT)

This QA inspector performed UT of the area previously tested and accepted by ZPMC Quality Control personnel.

This QA Inspector generated an UT report for this date. The member is identified as OBG Component. The weld

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

designation reviewed as follows:

BIKE PATH

BK3001-001-002; 003; 050; 051; 052; 053

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #004 located on Bike path component BK15C-001. Welder is identified as 057220. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2213-Tc-U4c.

Weld joint #002 located on Bike path component BK15C-001. Welder is identified as 057220. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2211-Tc-U4c.

Weld joint #003 located on Bike path component BK15C-001. Welder is identified as 057220. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2211-Tc-U4c.

Weld joint #001 located on Bike path component BK15C-001. Welder is identified as 057220. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2213-Tc-U4c.

Flux Cored Arc Welding (FCAW):

Weld joint #004 located on Bike path BK16A-001. Welder is identified as 057266. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Weld joint #005 located on Bike path BK16A-001. Welder is identified as 057266. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Submerged Arc Welding (SAW):

Weld joint #004 located on Bike path BK16B-001. Welder is identified as 207745. ZPMC Quality Control (QC) Inspector is identified as Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS-B-T-2221-Tc-U4a-S. (See attached photo)

BAY#11

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #017 located on SA6023B-001. Welder is identified as 044541. ZPMC Quality Control (QC) Inspector is identified as Shang Hai Lang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2212-Tc-U4c. (See attached photo)

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Weld joint #001 located on SA6020E-001. Welder is identified as 041271. ZPMC Quality Control (QC) Inspector is identified as Shang Hai Lang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2212-Tc-U4c.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Ho - 15000422372, who represents the Office of Structural Materials for your project.

Inspected By: Kumar,Sandeep

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer