

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022696**Date Inspected:** 06-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See Below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

CWI Inspector: Mr. Lv Li Qing

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Mr. Paul Dawson, arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. This QA Inspector observed the following:

OBG Bay 14

This QA Inspector observed ZPMC welder Mr. Wang Changfa, stencil 058102 used shielded metal arc welding procedure specification WPS-B-P-2212-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-046. This QA Inspector observed a welding current of approximately 170 amperes (amps), the base material had been preheated with electric heaters and Mr. Wang Changfa appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Wang Li, stencil 044772 used shielded metal arc welding procedure specification WPS-B-P-2212-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-156. This QA Inspector observed a welding current of approximately 180 amps, the base material had been preheated with electric heaters and Mr. Wang Li appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.



WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector observed ZPMC welder Mr. Yang Juping, stencil 051946 used shielded metal arc welding procedure specification WPS-B-P-2212-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019Y-058. This QA Inspector observed a welding current of approximately 180 amps the base material had been preheated with electric heaters and Mr. Yang Juping appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Yang Yunfeng, stencil 215553 used shielded metal arc welding procedure WPS-B-P-2212-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019Y-057. This QA Inspector observed a welding current of approximately 175 amps the base materials were preheated with electrical heaters and Mr. Yang Yunfeng appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ABF personnel performing ultrasonic inspections of OBG segment 14E weld SEG3019AZ-017. ABF appears to have marked multiple locations in this weld that appear to be ultrasonically unacceptable. See the photographs below for additional information.



Summary of Conversations:

See Above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey +8615000026784, who represents the Office of Structural Materials for your project.

Inspected By: Dawson,Paul

Quality Assurance Inspector

Reviewed By: Riley,Ken

QA Reviewer