

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023518**Date Inspected:** 09-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China**CWI Name:** Geng Wei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Structure**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Mr. Manuel Teall was present during the times noted above for observations relative to the work being performed at ZPMC.

BAY 14 -

Flux Cored Arc Welding (FCAW)

This QA Inspector observed the welding operation per the FCAW process in (2G) Position on a weld joint identified as SEG3019Y-066 .OBG 14E Segment . The welder is identified as 501946. ZPMC Quality Control (QC) is identified as Mr. Yuan Yuan. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-B-U2-FCM

Flux Cored Arc Welding (FCAW)

This QA Inspector observed the welding operation per the FCAW process in (2G) Position on a weld joint identified as SEG3019AA-014 .OBG 14E Segment . The welder is identified as 043661. ZPMC Quality Control (QC) is identified as Mr. Yuan Yuan. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-B-U3b-FCM

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SHIELDED METAL ARC WELDING (SMAW).

This QA Inspector observed the welding operation per the (SMAW) process in the (3G) Vertical position on a weld joint identified as DP3160-001-390 located on 14E. The welder is identified as 501946. The ZPMC Quality Control (QC) is identified as Mr. Yuan Yuan. The welding variables recorded by QC appeared to comply with WPS-B-P-2213-Tc-U4B-FCM-1

SHIELDED METAL ARC WELDING (SMAW).

This QA Inspector observed the welding operation per the (SMAW) process in the (4G) Overhead position on a weld joint identified as SEG 3019BB-045 located on 14E. The welder is identified as 037723. The ZPMC Quality Control (QC) is identified as Mr. Yuan Yuan. The welding variables recorded by QC appeared to comply with WPS-345-smaw-4G (4F)-FCM-repair-1.

On this date Caltrans OSM Quality Assurance (QA) Inspector ,Mr. Manuel Teall was present during the times noted above for observations relative to the work being performed at ZPMC

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Teall,Manuel	Quality Assurance Inspector
Reviewed By:	McClendon,Timothy	QA Reviewer
