

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/Ala Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024229**Date Inspected:** 29-May-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG Components	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

OBG Trial Assembly Area

In response to ZPMC NDT Inspection Notification Sheet #09299 for magnetic particle testing (MT) inspection of the following:

This QA Inspector performed random visual testing (VT) and then MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The members were identified as follows:

OBG Segment 13AE, SEG3007G. The weld designations reviewed was: 015, 014, 013, 011, 029, 030~043, 133, 040, 044, 045, 213, 049, 007, 010, 123, 124, 200, 201, 125, 126, 127, 128, 129, 130, 131, 132, 203~208. No apparent indications were observed.

OBG Segment 13AE, SEG3007AE. The weld designations reviewed were: 057, 058, 059, 060, 077, 078, 079, 080, 051~056, 071~076. No apparent indications were observed.

OBG Segment 13AE, FB3127A. The weld designations reviewed were: FB3127A001-029, 030, 033, 034. No apparent indications were observed.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

See photo below of this QA Inspector's symbol showing MT acceptance at one of the weld inspection locations.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 15000026784, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet, George	Quality Assurance Inspector
Reviewed By:	Riley, Ken	QA Reviewer
