

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
 690 Walnut Ave. St. 150
 Vallejo, CA 94592-1133
 (707) 649-5453
 (707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT**

Resident Engineer: Casey, William
Address: 333 Burma Road
City: Oakland, CA 94607

Report No: WIR-026282
Date Inspected: 13-Sep-2011

Project Name: SAS Superstructure
Prime Contractor: American Bridge/Fluor Enterprises, a JV
Contractor: American Bridge/Fluor Enterprises, a JV

OSM Arrival Time: 730
OSM Departure Time: 1600
Location: Job Site

CWI Name:	Chuck Kanapicki	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	S.A.S. components	

Summary of Items Observed:



The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI accompanied Caltrans representatives Tai Lin Liu, Thanh Le, Jason Wilcox and ABF representative Chuck Kanapicki in conducting the post arrival inspection of voyage 9 components. During the inspection, the QAI noted that painted surfaces have been marred from general shipping and handling and the contractor is aware of the necessary repairs. The QAI noted there does not appear to be other shipping related damage on OBG 14W. The QAI noted there are minor components that have not been examined for post arrival at this time. See the attached photos.

The QAI reviewed contract documents at pier 7. The QAI used approved weekly welding report submittals and cross referenced the welding and inspection status as reported with QA records to identify the overall weld status. The QAI received submittal 1536R75 and began reviewing the submittal for conformance with the contractor requirements. The QAI continued reviewing documents and compiling the weld status from documentation. This work was in progress at the end of the shift.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

The QAI relayed the status of the document reviews and post arrival inspection to the QAI Lead Bill Levell. Except as described above, there were no other notable conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Croff, Scott	Quality Assurance Inspector
Reviewed By:	Levell, Bill	QA Reviewer
