

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT**

Resident Engineer: Casey, William
Address: 333 Burma Road
City: Oakland, CA 94607

Report No: WIR-028625
Date Inspected: 18-Oct-2012

Project Name: SAS Superstructure
Prime Contractor: American Bridge/Fluor Enterprises, a JV
Contractor: American Bridge/Fluor Enterprises, a JV

OSM Arrival Time: 700
OSM Departure Time: 1330
Location: S.A.S. Job site

CWI Name:	N / A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	S.A.S. Structure	

Summary of Items Observed:

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.


The QAI made observations of the Parallel Wire Strand (PWS) Anchorages, East bound and West bound. The QAI noted that at each PWS there appears to be damage to the base metal and at several locations there is visible damage to the adjacent welds. Photos were taken to relay to the Assistant Structural Materials Representative (ASMR) Parinaz Aghili. The QAI noted that there will need to be additional surveying of the area and will continue this work during the next shift. See the attached photo.

The QAI reviewed contract documents at pier 7. The QAI used approved weekly welding report submittals and cross referenced the welding and inspection status as reported with QA records to identify the overall weld status. The QAI completed reviewing welding report submittal 1536R132 for conformance with the contract requirements.

The QAI noted that there are category B comments relating to the Electro-Slag Welds and inspection reports. Reference the TL-20 report for additional information. The QAI continued reviewing welding report submittal 1536R133. This work was in progress until the end of the shift.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

The QAI relayed the status of the document reviews and the observations of damage in the PWS Anchorages to the QAI Lead Danny Reyes. Except as described above, there were no other notable conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas, (916) 764-6027, who represents the Office of Structural Materials for your project.

Inspected By:	Croff, Scott	Quality Assurance Inspector
Reviewed By:	Reyes, Danny	QA Reviewer
