

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-029523**Date Inspected:** 01-Apr-2013**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1730**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Jobsite**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

At the start of shift, this Quality Assurance Inspector (QAI) traveled to the project site and observed the work and the inspection performed by American Bridge/Fluor Enterprises (AB/F) personnel. The inspection was performed on the various Complete Joint Penetration (CJP) groove welds of the East and West Orthotropic Box Girders (OBG's).

The welding was performed utilizing Shielded Metal Arc Welding (SMAW) process as per the Welding Procedure Specifications (WPS's).

At the start of the shift this QAI observed the following:

This QAI witnessed the Ultrasonic Testing (UT) inspection of Deck Access Hole (DAH) closure plate weld WB-PP116.5-W2 as performed by AB/F Quality Control (QC) Inspector Bernie Docena. This QAI performed UT verification inspection of this same weld. There were two (2) rejectable indications located by this QAI. See the attached TL-6027 UT report for details.

This QAI performed the Ultrasonic Testing (UT) verification inspection of the R1 Repair weld of the EB-SLLH-13 Lifting Rod deck closure plate. There were no indications noted. See the attached TL-6027 UT report for details.

Unless otherwise noted, all work observed on this date appeared to generally comply with the applicable contract documents.

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

The digital photographs below illustrate some of the work activities observed on this date:



## Summary of Conversations:

No significant conversations took place.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact SMR Gary Thomas (916) 764-6027, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Morris, Monty	Quality Assurance Inspector
<b>Reviewed By:</b>	Reyes, Danny	QA Reviewer

---