

DEPARTMENT OF TRANSPORTATION -Toll Bridge Program

333 Burma Rd.
Oakland, CA 94607
(510) 622-5660, (510) 286-0550 fax



*Flex your power
Be energy efficient!*

February 24, 2010

Contract No. 04-0120F4
04-SF-80-13.2 / 13.9
Self-Anchored Suspension Bridge
Letter No. 05.03.01-006871

Michael Flowers
Project Executive
American Bridge/Fluor, A JV
375 Burma Road
Oakland, CA 94607

Dear Michael Flowers,

Submittal 697, Rev. 4 – Paint Quality Work Plan (PQWP)

The Department has completed review of Submittal ABF-SUB-000697R04, "Paint Quality Work Plan (PQW) – ZPMC – Addendum – Surface Preparation & Painting Procedure," dated June 17, 2009. The submittal is "Approved as Noted," as shown in the attached document. This PQWP supersedes that approved in ABF-SUB-000697R02.

Please be aware that the following items remain outstanding/unresolved from State Letter 05.03.01-002869, dated October 23, 2008. These same comments apply to the review of Submittal ABF-SUB-000697R04.

1. *Provide the manufacturer's recommendations for the curing method outlined in section 8.4.6, "Curing," of the painting procedure prior to performing this operation.*
2. *Provide confirmation from the manufacturer that Interzinc 52 is compatible with Interzinc 22 prior to painting as this information is not provided on the data sheets.*
3. *Per the response to ABF-RFI-001527R00, provide documentation from the manufacturer that Intercure 200HS is suitable for galvanized surfaces.*

If you have any questions, please contact Brian Boal at (510) 622-5191.

Sincerely,

A handwritten signature in blue ink that reads "Gary Pursell".

GARY PURSELL
Resident Engineer

Attachment

cc: Rick Morrow; Brian Boal; Gary Lai; Mark Woods; Bill Howe; Pat Lowry
file: 05.03.01, 55.0697