

DEPARTMENT OF TRANSPORTATION -Toll Bridge Program

333 Burma Rd.

Oakland, CA 94607

(510) 622-5660, (510) 286-0550 fax

*Flex your power
Be energy efficient!*

January 18, 2011

Contract No. 04-0120F4

04-SF-80-13.2 / 13.9

Self-Anchored Suspension Bridge

Letter No. 05.03.01-008908

Brian A Petersen
Project Executive
American Bridge/Fluor, A JV
375 Burma Road
Oakland, CA 94607

Dear Brian Petersen,

Submittal 1918, Rev. 1 - OBG - Miscellaneous (SA, X) - Lift 12W - Cable Bracket Details

The Department has completed review of Submittal ABF-SUB-001918R01, "OBG - Miscellaneous (SA, X) - Lift 12W - Cable Bracket Details," dated January 04, 2011. The submittal is "Returned for Correction," as shown on the attached drawings and as outlined by the following comments:

CATEGORY A:

1. Provide a 60mm radius rathole in the web plate so that the web-to-side connection plate CJP can be terminated.
2. Revise the connection of the strongback to the cable bracket at PP116 per TC-RFI-246R1. Coordinate changes with those elements fabricated outside of ZPMC.
3. Revise seal plates to cover 60mm ratholes.

If you have any questions, please contact Gary Lai at the Working Drawing Campus.

Sincerely,

A handwritten signature in blue ink that reads "Gary Lai for".

WILLIAM S. CASEY
Construction Manager (OBG)

For: PETER SIEGENTHALER
Resident Engineer

Attachment

file: 05.03.01, 55.1918