

12-0M4304, Drainage System 36
Existing 84" CMPA Culvert, at pipe entrance Stat 0+00

Photo #5



Photo #6



12-0M4304, Drainage System 36
Looking southwest, existing 84" CMPA Culvert

Photo #7 - Pipe Joint Seal location



Photo #8 - Pipe Joint Seal location



12-0M4304, Drainage System 36

Looking southwest, existing 18" CSP Riser locations (System #35-a and #37-a) typical

Photo #9 - Proposed Welded Steel Pipe Liner location



12-0M4304, Drainage System 36

Looking northeast at existing 84" CMPA Culvert seam

Photo #10 - Proposed Patch Plate Location, typical



12-0M4304, Drainage System 36-segment f
Looking northeast at the junction of the existing and proposed invert paving location

Photo #11 taken 9/25/08



Photo #12

