


Existing Conditions



Proposed Conditions

figure 5: Aerial view of the causeway segment of Rte. 92 just west of Skyline Blvd. (Rte. 35n) showing proposed uphill slow vehicle lane.