

Russian River Bridge Update
July 26, 2006

- Deck girders between bents 2 and abutment 1 were set. Deck girder placement is 80% complete.
- Fontana Steel continued placing steel rebar for the mid-span diaphragms and retaining walls at abutments 1 & 11.