

## APPROVED INDEPENDENT TESTING LABORATORIES

**NOTE:** Recent amendments to Section 52 (Reinforcement) of the California Department of Transportation (the Department) Standard Specifications (2006), requires that testing on prequalification and production sample splices on reinforcing steel shall be performed at an approved independent testing laboratory and that this laboratory be selected from the Department's Pre-Qualified Products List. The Structural Materials Testing Branch from the Office of Structural Materials will be responsible for this list. Please follow the steps outlined in the Independent Testing Laboratory Qualification Requirements document to submit a request to be included in the Department's Pre-Qualified Products List. The document can be found at [http://www.dot.ca.gov/hq/esc/approved\\_products\\_list/](http://www.dot.ca.gov/hq/esc/approved_products_list/).

| <b>LABORATORY</b>                                  | <b>LOCATION</b>                                  | <b>CONTACT</b>                             | <b>CONDITIONAL APPROVAL UNTIL</b>   | <b>FULLY APPROVED UNTIL</b>   |
|--|--|--|---|---|
| <b>Arrow Inspection &amp; Testing, Inc.</b>        | 6515 Somerset Blvd.<br>Paramount, CA<br>90723    | Rene Mora                                  | July 13, 2012<br>Meets Sec 52-1.08c<br>A-D. Need Part E<br>ITL Requirements |   |
| <b>CEL Consolidated Engineering Laboratories</b>   | 534 23 <sup>rd</sup> Avenue<br>Oakland, CA 94606 | Jim Powers                                 |   | Aug. 19, 2013.<br>Meets Sec. 52-1.08c<br>A-D and ITL<br>Requirements  |
| <b>“G” Force Laboratory</b>                        | 8788 Balboa Avenue<br>San Diego, CA 92123        | Joe Bouknight                              | Aug. 26, 2012<br>Meets Sec. 52-1.08c<br>Need Part E of ITL<br>Requirements  |   |
| <b>MRT Mechanical Rebar Testing, Inc.</b>          | 355 S. Vasco Rd.<br>Livermore, CA<br>94550       | Tiffany Garland,<br>President              |   | April 14, 2013.<br>Meets Sec. 52-1.08c<br>A-D and ITL<br>Requirements |
| <b>Sequoia Consultants</b>                         | 361 W. Grove Ave<br>Orange, CA 92856             | Pri Desilva,<br>President                  | May 30, 2012<br>Meets Sec.52-1.08c<br>Need Part E of ITL<br>Requirements    |   |
| <b>SIT Southwest Inspection &amp; Testing, Inc</b> | 441 Commercial Way<br>La Habra, CA 90631         | Renan R. Cruz<br>Laboratory<br>Manager     |   | April 1, 2012.<br>Meets Sec. 52-1.08c<br>A-D and ITL<br>Requirements  |
| <b>TEI Testing Engineers, Inc.</b>                 | 2811 Teagarden St.<br>San Leandro, CA<br>94577   | Terry Eglund<br>Quality Systems<br>Manager |   | Nov. 30, 2012.<br>Meets Sec 52-1.08c<br>A-D and ITL<br>Requirements   |
| <b>Twining, Inc.</b>                               | 3310 Airport Way<br>Long Beach, CA<br>90806      | Linas Vitkus<br>Division<br>Manager        |   | April 12, 2013.<br>Meets Sec. 52-1.08c<br>A-D and ITL<br>Requirements |