

INFORMATION HANDOUT

AGREEMENTS

NOTICE TO OWNER

Chester Public Utility District - sewer
P.O. Box 503
Chester, CA 96020

NOTIFICATION NO. 02-2943

NOTICE TO OWNER

Chester Public Utility District - water
P.O. Box 503
Chester, CA 96020

NOTIFICATION NO. 02-2944

MATERIALS INFORMATION

SUMMARY OF EXISTING PAVEMENT INVESTIGATIONS

NOTICE TO OWNER

RW 13-4 (Rev. 1/2009)

NOTICE TO OWNER

Dist	County	Route	PM	E.A.	Project #
02	Plu	36	6.5/9.2	02-5E2101	0212000094
Federal Aid No.: N/A					
Owners File: N/A					
Date: March 1, 2012			Freeway: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

Number 02-2943

To: Chester Public Utility District - sewer
P.O. Box 503
Chester, CA 96020

Attention: Bill Turner

Because of the State Highway construction project: In Plumas County in or near Chester on State Route 36 at PM 6.5/9.2 (Pavement overlay)

Which affects your facilities: Sewer manhole covers

You are hereby ordered to: Adjust sewer manhole covers to grade at the locations shown on the attached Utility Plan L-1 and L-2.

Your work schedule shall be as follows: All work will be done by the State's contractor.


Note: An agreement has been made between the Chester Public Utility District and the State to have the above mentioned work done by the States contractor. States Resident Engineer shall contact the Chester Public Utility District representative Bill Turner (530) 258-2171 at least 48 hours prior to commencement of work.

Liability for the cost of the work is: 100% Owner liability as facilities were placed under State Encroachment Permit.

Contact Bill Walker at (530) 225-4517 if you have questions.

DISTRICT DIRECTOR

DISTRICT DIVISION CHIEF

By 
DISTRICT UTILITY COORDINATOR

CC: Design
R/W
Resident Engineer

THIS NOTICE DOES NOT CONSTITUTE A PERMIT. OBTAIN AN ENCROACHMENT PERMIT BEFORE STARTING WORK.

NOTICE TO OWNER

RW 13-4 (Rev. 1/2009)

NOTICE TO OWNER

Dist	County	Route	PM	E.A.	Project #
02	Plu	36	6.5/9.2	02-5E2101	0212000094
Federal Aid No.: N/A					
Owners File: N/A					
Date: March 1, 2012			Freeway: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

Number **02-2944**

To: Chester Public Utility District - water
P.O. Box 503
Chester, CA 96020

Attention: Bill Turner

Because of the State Highway construction project: In Plumas County in or near Chester on State Route 36 at PM 6.5/9.2 (Pavement overlay)

Which affects your facilities: Water valve covers

You are hereby ordered to: Adjust water valve covers to grade at the locations shown on the attached Layout Sheets L-1 and L-2 provided by the State.

Your work schedule shall be as follows: All work will be done by the State's contractor.


Note: An agreement has been made between the Chester Public Utility District and the State to have the above mentioned work done by the States contractor. States Resident Engineer shall contact the Chester Public Utility District representative Bill Turner (530) 258-2171 at least 48 hours prior to commencement of work.

Liability for the cost of the work is: 100% Owner liability as facilities were placed under State Encroachment Permit.

Contact Bill Walker at (530) 225-4517 if you have questions.

DISTRICT DIRECTOR

DISTRICT DIVISION CHIEF

By 
DISTRICT UTILITY COORDINATOR

CC: Design
R/W
Resident Engineer

THIS NOTICE DOES NOT CONSTITUTE A PERMIT. OBTAIN AN ENCROACHMENT PERMIT BEFORE STARTING WORK.

SUMMARY OF EXISTING PAVEMENT INVESTIGATIONS

Investigations carried out on the existing road, Plu-36-PM 6.5/9.2, indicate that these materials are suitable for cold in-place recycling. Coring tests conducted on subject roadbed indicate that the engineering properties of these materials may be improved to provide sufficient strength required to extend the life of this pavement for 10 to 20 years by recycling the upper 0.30' with asphalt emulsion and capping with 0.25' of hot mix asphalt (Type A).

The general structural section, from the bottom up, is either native material or aggregate base then asphalt concrete. Cores indicated that the depth of asphalt concrete ranged from 0.30' to 1.00'. Core samples taken were uniform in appearance.

The existing AC appears to be distressed.

Any reliance placed by the Contractor on this information shall be at their own risk and they shall undertake their own separate testing program to determine the materials present and conditions prevailing at the time of construction.