

**DEPARTMENT OF TRANSPORTATION**  
DIVISION OF ENGINEERING SERVICES  
OFFICE ENGINEER, MS 43  
1727 30<sup>th</sup> STREET  
P. O. BOX 168041  
SACRAMENTO, CA 95816-8041  
PHONE (916) 227-6300  
FAX (916) 227-6282  
TTY 711



*Flex your power!  
Be energy efficient!*

February 1, 2012

Facsimile: (831) 384-5078

Peter J. Taormina, Manager  
Monterey Peninsula Engineering  
P. O. Box 400  
Marina, CA 93933

04-2A2604  
04-SCI-152-12.6/13.0  
B.O. 1/25/12

Dear Mr. Taormina:

Monterey Peninsula Engineering (MPE) submitted a bid on contract 04-2A2604 on January 25, 2012. By this letter, the Department notifies MPE that its bid is non-responsive because it failed to properly submit the Subcontractor List.

The Subcontractor List form states in part,..."Complete columns 1 and 4 and submit with the bid. Complete columns 2 and 3 and submit with the bid or fax to (916) 227-6282 within 24 hours after the bid opening. Failure to provide complete information in columns 1 through 4 within the time specified will result in a non-responsive bid." MPE failed to submit the bid item numbers and percent of bid item subcontracted, as required in columns 2 and 3.

Based on the above, the Department finds your bid is non-responsive. The Department will proceed to award the contract to the lowest responsible bidder provided all requirements are met.

If you have any questions, please contact Tammy Thomas, Contract Awards Branch Chief, at (916) 227-6228.

Sincerely,

A handwritten signature in black ink, appearing to read "John C. McMILLAN".

*Per* JOHN C. McMILLAN  
Deputy Division Chief  
Office Engineer  
Division of Engineering Services

Attachment

B

STATE OF CALIFORNIA - DEPARTMENT OF TRANSPORTATION  
**SUBCONTRACTOR LIST**  
DES-OE-0102.2 (REV 3/2011)

Bidder Name: Monterey Peninsula Engineers

The bidder must identify each subcontractor performing work in an amount in excess of 1/2 of 1 percent of the total bid or \$10,000, whichever is greater (Pub Cont Code § 4100 et seq.). Complete columns 1 and 4 and submit with the bid. Complete columns 2 and 3 and submit with the bid or fax to (916) 227-6282 within 24 hours after the bid opening. Failure to provide complete information in columns 1 through 4 within the time specified will result in a nonresponsive bid.

Column 1: Business Name and Location	Column 2: Bid Item Nos.	Column 3: Percentage of Bid Item Subcontracted	Column 4: Description of Subcontracted Work
• Chrisp Company Fremont, CA			Striping
• Green Vista Landscape Rocklin, CA			Erosion Control
• Darrel Barni Electric Watsonville, CA			Electrical
Cyclone Fence San Martin, CA			Fence
BD Banggaard Construction Livermore, CA			Concrete

For individuals with sensory disabilities, this document is available in alternate formats. For information call (916) 654-6410 or TDD (916) 654-3880 or the Records and Forms Management, 1120 N Street, MS-89, Sacramento, CA 95614.

11

**\*\* Transmit Conf. Report \*\***

P. 1  
CAL/TRANS CONTR AWARDS Fax 916-227-6282

Feb 1 2012 12:12pm

Fax/Phone Number	Mode	Start	Time	Page	Result	Note
918313845078	Normal	01:12:11pm	0'29"	2	# 0 K	

STATE OF CALIFORNIA—BUSINESS, TRANSPORTATION AND HOUSING AGENCY

EDMUND G. BROWN Jr., Governor

**DEPARTMENT OF TRANSPORTATION**  
DIVISION OF ENGINEERING SERVICES  
OFFICE ENGINEER, MS 43  
1727 30<sup>th</sup> STREET  
P. O. BOX 168041  
SACRAMENTO, CA 95816-8041  
PHONE (916) 227-6300  
FAX (916) 227-6282  
TTY 711



*Flex your power!  
Be energy efficient!*

February 1, 2012

Facsimile: (831) 384-5078

Peter J. Taormina, Manager  
Monterey Peninsula Engineering  
P. O. Box 400  
Marina, CA 93933

04-2A2604  
04-SCI-152-12.6/13.0  
B.O. 1/25/12

Dear Mr. Taormina:

Monterey Peninsula Engineering (MPE) submitted a bid on contract 04-2A2604 on January 25, 2012. By this letter, the Department notifies MPE that its bid is non-responsive because it failed to properly submit the Subcontractor List.

The Subcontractor List form states in part, "... Complete columns 1 and 4 and submit with the bid. Complete columns 2 and 3 and submit with the bid or fax to (916) 227-6282 within 24 hours after the bid opening. Failure to provide complete information in columns 1 through 4 within the time specified will result in a non-responsive bid." MPE failed to submit the bid item numbers and percent of bid item subcontracted, as required in columns 2 and 3.

Based on the above, the Department finds your bid is non-responsive. The Department will proceed to award the contract to the lowest responsible bidder provided all requirements are met.

If you have any questions, please contact Tammy Thomas, Contract Awards Branch Chief, at (916) 227-6228.

Sincerely,

*pc* JOHN C. McMILLAN  
Deputy Division Chief  
Office Engineer  
Division of Engineering Services

Attachment