

Memorandum

*Serious drought.
Help Save Water!*

To: RICK GUEVEL
Chief
Office of SHOPP Management

Date: May 15, 2014

File: SHOPP Amendments
14H-035

From: DEPARTMENT OF TRANSPORTATION
Division of Transportation Programming
MS-82

Subject: Amendments to the 2014 SHOPP

RECOMMENDATION

I recommend that the following 2014 SHOPP Amendments be approved:

- **SHOPP Amendment 14H-035**
Amends the 2014 State Highway Operation and Protection Program by incorporating project cost, scope, schedule and technical changes as shown in the Attachment.

Approved:

Original Signed By
DONNA M. BERRY
SHOPP Statewide Development

Original Signed By
RICK GUEVEL
Chief
Office of SHOPP Management

Attachment

cc: DISTRICT DIRECTORS (1, 2, 4 & 10)

2014 SHOPP Amendment 14H-035
Cost, Scope, Schedule and Technical Changes
Includes Federal Emergency Relief Funds
(\$ Thousands)

| Dist | County | Route | Post Miles | Location/Description | PPNO | EA | EFIS# | Prog | RW | Const | FY | Support | | | Comments |
|------|---------------|-------|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-------|-------------------------------------|---------|---------|------------------|----------------|------------------------------|------------------------------|------------------------------|-----------------------------------------------|
| 01 | Humboldt | 299 | 25.0/25.7 | Near Willow Creek, from 0.4 mile to 1.1 miles east of Chezem Road. Curve improvement. | 23.8 | 0A490 | 0100020308 | 201.010 | 63 | 4,071 | 14/15 15/16 | PA&ED PS&E RW Const | 428 622 52 368 | 428 622 52 368 | Update schedule. |
| 02 | Shasta | 299 | 77.8/79.7 | Near Burney, from west of Sonoma Street to west of Route 89. Rehabilitate roadway. | 3449 | 4E020 | 0200020196 | 201.120 | 51 | 7,500 | 17/18 | PA&ED PS&E RW Const | 500 580 100 1,000 | 500 580 100 1,000 | Technical correction to Location/Description. |
| 02 | Shasta | VAR | | In Shasta, Butte, Lassen and Plumas Counties at various locations. Pave shoulder and install lighting and signage at chain control locations. | 3479A | 4E812 | 0214000051 | 201.235 | 60 | 3,300 | 14/15 | PA&ED PS&E RW Const | - | 400 600 100 600 | Split from PPNO 3479 |
| 04 | Marin | 1 | 8.1 | Near Muir Beach, at Cold Stream Road. Construct retaining wall. | 0308J | 4S660 | 0400001256 | 201.131 | 100 | 1,675 2,200 | 14/15 15/16 | PA&ED PS&E RW Const | 850 400 50 335 | 850 600 100 515 | Update cost and schedule. |
| 04 | San Francisco | 280 | R4.2/R6.6 | In San Francisco, at Southern Viaduct Bridge #34-0046. Rehabilitate bridge deck. | 0608K | 2A490 | 0400000827 | 201.110 | 432 | 40,365 10,730 | 14/15 15/16 | PA&ED PS&E RW Const | 605 2,247 755 1,732 | 605 2,247 755 1,732 | Update cost and schedule. |
| 04 | San Mateo | 280 | R0.3/R27.1 | Near Stanford, from Route 1/280 Junction to San Francisquito Creek at various locations; also near Lincoln, on Route 92 at PM 14.4. Upgrade metal beam guardrail transition railing. | 0730B | 1G830 | 0400020615 | 201.015 | 6 10 | 2,260 3,300 | 14/15 | PA&ED PS&E RW Const | 297 594 297 890 | 297 745 90 620 | Update cost and schedule. |
| 10 | Merced | 5 | 21.4 | In Santa Nella, at the San Luis Wasteway Bridge No. 39-0167L/R. Repair Bridge deck, approach, and departure slabs. | 3064 | 0X610 | 1013000034 1013000003 | 201.119 | | 2,201 | 14/15 | PA&ED PS&E RW Const | 20 70 10 450 | 20 70 10 450 | Technical correction to EFIS #. |

2014 SHOPP Amendment 14H-035
 Cost, Scope, Schedule and Technical Changes
 Includes Federal Emergency Relief Funds
 (\$ Thousands)

| Dist | County | Route | Post Miles | Location/Description | PPNO | EA | EFIS# | Prog | RW | Const | FY | Support | | | Comments |
|------|-------------|-------|------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------|-------------------------------------|---------|----------------------|-------------------------|-------|------------------------------|-------------------------|-------------------------|------------------------------------------------------------|
| 10 | San Joaquin | 4 | R16.2 | In Stockton, at the connector ramp from westbound eastbound Route 4 to southbound Route 5. Place high friction surface material and upgrade Upgrade guardrail and signs. | 3014 | 0W110 | 1000020426 | 201.010 | 200 28 | 600 2,160 | 14/15 | PA&ED PS&E RW Const | 250 400 25 260 | 250 400 25 260 | Technical correction to Location/Description. Update cost. |
| 10 | San Joaquin | 120 | 6.5/16.7 | In and near Manteca, from west of Vasconcellos Avenue to west of Escalon Bellota/McHenry Avenue. Rehabilitate pavement. | 3062 | 0Y950 | 1014000064 1014000070 | 201.121 | 20 | 3,700 | 14/15 | PA&ED PS&E RW Const | 30 110 10 300 | 30 110 10 300 | Technical correction to EFIS #. |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |