

**2015 FSTIP  
Rural Non-MPO Areas  
Grouped Project Listing  
SHOPP Bridge Rehabilitation and Reconstruction**

**CTIPS ID: 230-0000-0065**  
(Cost x \$1,000)

Dist	County	Route	EA	Description	FY 14/15	FY 15/16	FY 16/17	FY 17/18	Total	Comments
1	DN	101	43640	Near Crescent City from 0.2 mile north of the Smith River Overflow Bridge. Replace bridge.	-	-	71,568	-	71,568	
1	DN	101	0B090	Near Klamath, at Panther Creek Bridge No. 01-0025 and at Hunter Creek Bridge No. 01-0003. Seismic retrofit.	-	-	-	28,413	28,413	
1	DN	VAR	0A100	In Del Norte County, on Route 101 at Railroad Avenue Overcrossing No. 01-0063, Smith River Overflow Bridge No. 01-0046, Rowdy Creek Bridge No. 01-0023; also on Route 199, at Route 199/101 Connector Overcrossing No. 01-0058F and Middle Fork Smith River	-	21,472	-	-	21,472	
1	HUM	101	29611	Near McKinleyville, from 0.2 mile south to 0.6 mile north of Mad River Bridge; also on Route 200 from St. Maru Lane to Reserve Road (PM R0.3/0.5). Required environmental mitigation for EA 29610.	-	711	-	-	711	
1	HUM	101	0A110	Near Fortuna, at South Fork Eel River Bridge No. 04-0123 and Eel River Bridge No. 04-0016R. Seismic retrofit.	-	-	-	9,327	9,327	
1	HUM	101	0E000	Near Eureka, from postmile 79.9 to 84.7. Replace bridge rails on Gannon Slough Bridge No. 04-0024R, replace guard rail on Eureka Slough Bridge No. 04-0022L and replace Jacoby Creek Bridge No. 04-0023L. Upgrade bridge rails and replace bridge.	-	-	7,732	-	7,732	
1	HUM	101	0E230	Near Scotia, at Eel River Overhead No. 04-0014. Rehabilitate bridge deck.	3,096	-	-	-	3,096	
1	HUM	254	43060	Near Phillipsville, from Ohman Creek Bridge to Bear Creek Bridge at various locations. Replace bridge rails and widen shoulder.	-	10,509	-	-	10,509	
1	HUM	0E100	VAR	In Humboldt County near Hoopa on Route 96 at Trinity River Bridge (PM 12.3) and near Arcata on Route 101 at Arcata overhead (PM 87.8)	-	-	3,231	-	3,231	
1	LAK	29	38560	Near Middletown, at St. Helena Creek Bridge No.14-0052. Scour prevention.	857	-	-	-	857	
1	MEN	1	40110	Near Albion, from 3.0 miles north of route 128 junction to 0.2 mile north of Albion river Bridge No. 10-0136. Bridge Replacement.	-	65,962	-	-	65,962	
1	MEN	1	40140	Near Albion, from 2.2 miles north of Route 128 junction to 0.2 mile north of Salmon Creek Bridge No. 10-0134. Bridge replacement.	-	71,821	-	-	71,821	
1	MEN	1	43480	In and near Fort Bragg at Little River Bridge No. 10-0178, at Jack Peters Bridge No. 10-0150, at Russian Gulch Bridge No. 10-0151, and at Pudding Creek Bridge No. 10-0158. Upgrade and replace barrier rails.	-	19,016	-	-	19,016	
1	MEN	101	29302	Near El Roble, at Robinson Creek Bridge No. 10-0005L and Willits Overhead Bridge No. 10-0001. Upgrade barrier rail and widen bridge.	-	6,577	-	-	6,577	
1	MEN	101	0C370	Near Leggett, at Cedar Creek Arch Culvert. Repair arched culvert bridge.	-	5,157	-	-	5,157	
1	MEN	271	0A840	Near Piercy, from 0.7 mile north of Routes 271/101 separation Bridge No. 10-0217 to 0.4 mile south of Sidehill Viaduct No. 10-0100. Replace bridge.	-	-	-	8,873	8,873	
1	MEN	VAR	0C430	On Route 101, in Willits; On Route 128, 34.1 miles west of Ukiah; also on Route 20, 8.5 miles east of Route 101/20 Junction. Scour mitigation.	-	-	2,038	-	2,038	
1	MEN	VAR	0E240	In Mendocino County, at various routes and at various locations. Mitigate environmental impacts.	-	-	-	5,776	5,776	
2	LAS	36	4F560	Near Westwood, at Goodrich Creek Bridge No. 07-0048. Replace bridge.	-	-	-	4,645	4,645	
2	MOD	299	4F570	Near Canby, at Caldwell Creek Bridge No. 03-0028. Replace bridge.	-	-	-	3,320	3,320	
2	MOD	299	4F210	Near Adin, at Butte Creek Bridge No. 03-001 and at Ash Creek Bridge No. 03-002. Replace bridges.	-	-	-	8,357	8,357	
2	PLU	70	2C090	Near Quincy, from 0.6 mile west to 0.5 mile east of Spring Garden Bridge Overhead. Replace bridge.	-	20,840	-	-	20,840	
2	PLU	70	1C750	Near Belden, at Yellow Creek Bridge #09-0008. Replace bridge.	-	-	13,420	-	13,420	
2	PLU	89	0E180	Near Canyon Dam, at Lake Almanor Spillway. Replace bridge.	-	13,360	-	-	13,360	
2	PLU	147	4E640	Near Canyon Dam, from 0.1 mile south to 0.4 mile north of Hamilton Branch Bridge. Replace bridge.	13,023	-	-	-	13,023	
2	SIS	5	3E730	Near Yreka, at Hill Road Overcrossing No. 02-0130. Replace bridge.	9,006	-	-	-	9,006	
2	SIS	5	4F540	Near Weed, from north of Deetz Road Undercrossing No. 02-0161 to north of Black Butte Overhead No. 02-0004. Bridge replacement.	-	-	-	12,598	12,598	
2	SIS	5	4F580	Near Hornbrook, from Klamath River Bridge No. 02-0134 to north of Route 96. Rail upgrade and bridge deck rehabilitation.	-	-	5,895	-	5,895	
2	SIS	5	4G240	Near Edgewood, from 0.4 mile south to 0.4 mile north of North Edgewood Overhead #02-0032L&R. Strengthen and upgrade bridges.	-	-	6,549	-	6,549	
2	SIS	5	4G230	Near Hornbrook, at Klamath River Road Undercrossing #02-0133L&R. Strengthen and upgrade bridges.	-	-	3,432	-	3,432	
2	SIS	89	4F550	Near McCloud, at Mud Creek Bridge No. 02-0046. Replace bridge.	-	-	-	4,521	4,521	
2	SIS	96	4E650	Near Seiad Valley, at various locations from Slater Butte Road to 0.1 mile west of Beaver Creek Bridge. Upgrade bridge rail.	-	14,048	-	-	14,048	
2	SIS	263	2E480	Near Yreka, at Klamath River Bridge. Replace bridge.	-	-	-	14,310	14,310	
2	TEH	5	4F590	In Red Bluff, at Sacramento River Bridge No. 08-0095R/L. Retrofit Bridges.	-	-	-	28,236	28,236	
3	GLE	5	0F370	Near Willows, from County Road 16 overcrossing to County Road 3 overcrossing. Raise structures for vertical clearance.	10,984	-	-	-	10,984	
3	NEV	80	3F050	In Nevada and Placer Counties, on routes 80 and 89 at South Yuba River Bridge near Emigrant Gap and Prosser Creek Bridge near Truckee. Seismic retrofit bridges.	-	6,360	-	-	6,360	
10	TUO	120	0L970	Near Moccasin, east of Yosemite Junction at James E. Roberts Memorial Bridge No. 32-0018. Replace deck and retrofit bridge.	19,484	-	-	-	19,484	
<b>Total</b>					<b>56,450</b>	<b>255,833</b>	<b>113,865</b>	<b>128,376</b>	<b>554,524</b>	