


EA	04-0120F4
Co-Rte-KP (PM)	SF-080-13.2/13.9 (8.2/8.7)
Structure Rep.	Rick Morrow




File Name:	DSC00385
Date:	12-17-07
By Int:	SH Song

Description: 2x16-43B4T01* bar placement near southeast corner of W2 cap beam.

File Name:	DSC00390
Date:	12-17-07
By Int:	SH Song

Description: Placement of B4 #43 transverse bars near the east sloping bulkhead forms and getting ready to place bars on the east sloping bulkhead forms.



File Name:	DSC00392
Date:	12-17-07
By Int:	SH Song

Description: Jason Jobe was the operator of the torque wrench today and the mechanical couplers were spray painted white to denote that he did the work.

File Name:	DSC00395
Date:	12-17-07
By Int:	SH Song

Description: Access ramp that was built Friday December 14, 2007 to facilitate a safe entry to work area.