



EA	04-0120F4
Co-Rte-KP (PM)	SF-080-13.2/13.9 (8.2/8.7)
Structure Rep.	Rick Morrow



File Name:	DSC00431
Date:	12-26-07
By Int:	M Bruce

Description: Removal of B3 #43 transverse bars, which were 3m short of the specified length.

File Name:	DSC00432
Date:	12-26-07
By Int:	M Bruce

Description: Continued placement of CBT transverse tendon ducts.