

Contract No. 04-0120F4
04-SF-80-13.4, 13.8
ACBRIM-080-(094)N

Report No. 706
Date 4/22/2008
M W Th F S S Circle Day
Shift Hr Start 0630 Stop 1530

ASSISTANT RESIDENT ENGINEER'S DAILY

E2 Crossbeam

REPORT

Location & Description of Operation Setting sandjacks on the E2 footing.

EQUIPMENT AND/OR LABOR:			HOURS - ITEM NO.							WEATHER	
EQPT. NO.	No. Men	DESCRIPTION (of Equipment or Labor)	Regular Hours	OT						55 deg	
			IDLE OR DOWN							REMARKS for Idleness or remarks)	(Reason other)
ABF		Pile Driver- Foreman	For personelle hours please see							Ben Neal	
ABF		Pile Driver-Journeyman	M. Modanlu's diary							Allen Briney	
ABF		Pile Driver-Journeyman								Jason Matlock	
ABF		Pile Driver-Journeyman								Luke Paulk	
ABF		Operator-Oiler								Kevin Alger	
ABF		Operator-Journeyman								Kevin Fitzgerald	
ABF		Crane - "Ringer"								Barge #1 - Manitowac	
481-93-4002		Man Lift								Genie	
P185R		Compressor								Ingersoll-Rand	
Vantage500		Welding Machine								Lincoln Electric	
Vantage500		Welding Machine								Lincoln Electric	
MQ		Generator								Denyo	
MQ		Generator								Denyo	
ABF		Equipment Barge								Flex Anchor	
ABF		Skiff								115 Horse	
ABF		Water Tank									
972279-549		Grout Mixer									

In the morning I met with KFM and the E2-T1 personnel to go over outstanding EWB issues. M. Modanlu covered the field work for the day.

I visited E2 in the afternoon with G. Klebanov, and S. Soheili. G. Klebanov and S. Soheili checked the elevations of the sandjack locations.

The crew was in the process of grouting the bearing pads for the sandjacks. The surveyor checked the elevations of all four of the northern jacks, and ok'd them to pour. All Hilti bolts that are installed are embedded to a depth of a least 6" except for one (#6) which has roughly 5". Crew has changed their drilling strategy and now is getting much better results with straightness and depth.

An ISI inspector was onsite to take grout cubes for the the bearing pad grout.

During the pouring of grout in sandjack #2, there was an incident between M. Modanlu and Ben Neal. Masoud touched B. Neal on the face during a conversation. I witnessed this interaction and there were no ill intentions meant by Masoud that I could tell. The gesture was in a friendly manner. Ben took offense to this and voiced his opinion to me. I informed Masoud that this gesture was interpreted as offensive by Ben and should not be repeated. Masoud then respectfully approached Ben to let him know that he understood his concern and that it would not happen again. No other incidents followed for the rest of the day. All parties seemed to have reached an understanding.



Aaron J. Prchlik

T.E.

Signature

Title

REC'D - 08 MAY - 2008 #04224