

04-0120F4
04-SF, ALA-80-
12.2/14.3, 0.0/2.7

STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION

File: 46.

Page 1 of 2

Assistant Resident Engineer

Report

SFOBB East-Span
Seismic Retrofit
Project (SAS)

Robert Kobal

Week of 2013-1-21

SAS Bridge Travelers/Skyway cleanup

Mon 2013-1-21

Holiday

ABF did the final install of the hinge cover plates at hinges B and C, applying locktite to the bolts. They removed rain water that has previously accumulated through the bolt holes by pumping it out through the bolt holes at the top and the bottom drain plugs previously installed. The water removal is extra work to be charged to CCO 217 (copy of extra work bill attached).

M Chamberlin- 4 hours+1OT,

B Chapman 1 OT,

J Filstrup 1 OT,

M Perry 1 OT,

Equipment at 5 hours each: Pickup truck, Kubota buggy and generator.

Tue 2013-1-22

Attended corridor coordination meeting

Prepared for and lead the Skyway cleanup meeting, see meeting minutes.

Worked on BASE presentation for BATA.

Reviewed CCO217S1 revised plan sheets and approved to Authorize To Proceed to the contractor.

Wed 2013-1-23

Sick leave.

I attended the BATA meeting. The BATA board approved the funding for the BASE cameras.

ABF did the final install of the hinge cover plates at hinges D, applying locktite to the bolts. They removed rain water that has previously accumulated through the bolt holes by pumping it out through the bolt holes at the top and the bottom drain plugs previously installed. The water removal is extra work to be charged to CCO 217 (copy of extra work bill attached).

M Chamberlin- 5 hours,

B Chapman 3 hours,

J Filstrup 3 hours,

M Perry 3 hours,

Equipment for 5 hours each: Pickup truck, Kubota buggy and generator.

13 APR - 3 AM 10:48 25913

ARE Report (continued)
SAS Bridge Travelers/Skyway cleanup
Robert Kobal

Page 2 of 2

Thur 2013-1-24

Sick leave.

Prepared for and lead by phone the Traveler meeting- see meeting notes.

Friday 2013-1-25

Attended OBG staff meeting.

Worked on CCO 272 estimate.

Conducted tour of bridge and some of the security areas for CHP and separately for Headquarters Maintenance.



Robert Kobal
Senior TE

