

P.O. BOX 23223 Oakland, CA 94623  
Phone (510)419-0120 / Fax (510)839-0666

**Request for Information (RFI) Report**  
**KFM Skyway Project # 04-012024**

*Run Date 22-Jan-03*  
*Time 3:10 PM*

Dated: 22-Jan-2003

To: Doug Coe  
Caltrans-Skyway Project  
345 Burma Road  
Oakland CA 94607  
Phone: (510) 622-5100 Fax: (510) 622-5165

RFI No: KFM-RFI-000495 Rev: 00  
Co/Job # 364-3726  
Contract # 04-012024  
Sub/Supplier: KOS  
Sub/Supplier No: 49R1

Date Requested By: 29Jan-2003

Group: FND

Subject: Caltrans NCR on IQI placement of film

Drawing No. Ref:

Specification Ref: 08-3.01

Other:

Resubmittal/Supplement Ref:

Description (Attachments As Needed):

Please see attached KOS RFI # 41 and Respond

Potential Time Impact? Yes

Potential Cost Impact? Yes

Schedule Activity ID#:

General Explanation of Potential Impact (If Required):

**Response (Attachments As Required):**

Answered By:

Date Answered:

CC:

Prepared By: Robb Swenson  
Originator

Reviewed By:   
Scott Hanson

Reviewed By:   
John Hassard

Submitted By:   
Contract Admin/DCS Staff

RECEIVED  
004265 JAN 23 03

56.495

# Kiewit Offshore Services

## REQUEST FOR INFORMATION

P.O. Box K  
INGLESIDE, Texas 78362

Phone: 361-775-4300

No. 00049

Rev. 

**TITLE:** IQI Placement on Film

**DATE:** 12/23/2002

**PROJECT:** SFOBB Footing Fabrication

**JOB:** 3657

**TO:** Attn: Robb Swenson  
Kiewit/FCI/Manson  
220 Burma Road  
Oakland, CA 94649  
Phone: 510-419-0120 Fax: 510-839-0666

**STARTED:**  
**COMPLETED:**  
**REQUIRED:** 12/30/2002

### REQUEST:


Caltrans NCR on IQI placement on film.

Caltrans inspectors have written an NCR regarding the placement of IQIs'. KOS agrees that the IQIs' are not as per Figure 6.1A of AWS D1.5-96. However, the ability to read and interpret this film is not hindered by the incorrect placement of the IQIs' on the film already shot.

KOS is requesting that the film already shot with the IQI spacing not exceeding 250 mm be accepted as is.

Please advise.

**Requested By:** Kiewit Offshore Services

**Signed:**   
Brad Dearing

**Date:** 4/19/03

Expedition ©

### ANSWER:

**Answered By:** Kiewit/FCI/Manson

**Date:** \_\_\_\_\_

**Signed:** \_\_\_\_\_  
Robb Swenson

**DEPARTMENT OF TRANSPORTATION**

SFOBB – Skyway Project  
345 Burma Road  
Oakland, CA 94607  
Facsimile Number: (510) 622-5165



*Flex Your Power  
Be Energy Efficient!*

January 28, 2003

KFM, a JV  
P.O. Box 23223  
Oakland, CA 94623

Contract: 04-012024  
04-SF, Ala-80-13.9/14.3, 0.0/1.6  
SFOBB Skyway Project

*State Letter # 5.03.1-001085*

*Subject: Response to RFI 495 -- (KOS RFI 49, Rev. 1) Caltrans NCR on IQI placement of film*

Dear Mr. Skoro,  
Attention: Rich Bienek and Robb Swenson,

KOS RFI 49, rev 1, received on January 23, requests that the Radiographic film which has incorrectly placed IQIs which are not placed in accordance with Figure 6.1A of AWS D1.5-96 be accepted for all film shot prior to the December 19, 2002 NCR, where the IQI spacing does not exceed 250mm. If the film already shot prior to the NCR is acceptable in all other respects, and the ability to read and interpret this film is not hindered by the incorrect placement of the IQIs and because the IQI placement is now in conformance with Figure 6.1A of AWS D1.5-96, this proposal is acceptable. If you have any questions regarding this matter, please contact Mark Woods at (510) 622-5107.

Sincerely,

A handwritten signature in black ink, appearing to read "Mark P. Woods".

Mark P. Woods  
Foundation Structure Representative

for: Douglas B. Coe  
Resident Engineer

c: Y. Lin, D. Coe,  
V. Iyer, M. Dunn

file: 5.03.1, 9.03.2, 9.10.2