



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
May 26

Repair Work

Devil's Slide (post mile 39.14)

- Below the road, drill and install work for rock dowels continues.



Portable light rig suspended from crane to illuminate rock dowel work area at night.



Night crew performing rock dowel work.

- With rebar work finished, shotcreting for the north portion of whaler wall A started to-day. The photograph below shows only a portion of the first bracing wall below the road. The wall is being constructed in sections to avoid interfering with rock dowel work.



Shotcrete work on the north portion of wall A

Traffic

- Signs preventing right turns on red between 5:00 a.m. and 9:00 a.m. Monday through Friday were installed at the intersection of Capistrano and Highway 1 to-day.



No right on red turn signs at Capistrano.

- Additional detour sign installed in Pacifica for Highway 1 south bound motorists.



- Detour information installed in Montara for northbound motorists on Highway 1.

