



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
May 31

### **Repair Work**

Devil's Slide (post mile 39.14)

- Rock dowel drilling and installation continued to-day.
- Condon and Johnson continued drilling for the 150 feet long tie backs at whaler wall 'A' north.
- Excavation for the north section of whaler wall 'A' started to-day.

### **Traffic Information**

- Additional road closure signs are being fabricated.
- Caltrans bicycle coordinator is working with several cycling groups to develop detour signs and maps.