



# Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update  
June 1

## Repair Work

Devil's Slide (post mile 39.14)

- Rock dowel installation below the road is now complete.



Overnight rock dowel installation below the road.

- Work started on securing steel netting above the road. The netting is attached to rock anchors drilled about 20 feet deep and is needed to prevent loose rocks falling onto the highway.



Installing rock anchors to secure steel netting above the road.

- Excavation for whaler wall 'A' continued to-day.



Continuing excavation for the first wall below the road.

- Layout for the second bracing wall above the road, wall 'D', began to-day.



Layout for wall 'D'

- Drilling and installation of 150 feet log tie backs continued to-day at the north end of whaler wall 'A'.



Right foreground, drilling for tie backs while crews continue to construct bracing wall 'A'. Background right, slope surface secured by a layer of shotcrete.