



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 2

Repair Work

Devil's Slide (post mile 39.14)

- Shotcreting below the road continued to-day
- Rebar installation and shotcreting another section of whaler wall 'A' took place.



Rebar and concrete work taking place simultaneously on a section of whaler wall 'A'.

- Drilling and installation of tie backs for wall 'A' continued.



150 feet long tie backs installed through wall 'A'.



Equipment for mixing and pumping grout to secure tiebacks in place.



Right foreground, drilling for tie backs while crews continue to construct bracing wall 'A'. Background right, slope surface secured by a layer of shotcrete.