



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 8

Repair Work

Devil's Slide (post mile 39.14)

- Whaler wall construction above and below the road:
Whaler wall 'A' below the road – foundation excavation, rebar installation and concrete work taking place simultaneously on different sections.

Whaler wall 'D' above the road – installing formed rebar and concrete work taking place.
- Drilling and tie back installation:
'Condon & Johnston' continued tie back work on wall 'A' below the road. 22 out of 59 now complete.

'Drill Tech' continued drilling for tie backs at wall 'C'. 6 out of 34 now complete.
- Re-paving work is complete.