



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
June 12

### Repair Work

Devil's Slide (post mile 39.14)

- Whaler wall construction above and below the road:
  - Whaler wall 'A' below the road – this wall was completed to-day.
  - Whaler wall 'D' above the road – installing formed rebar and concrete work continued. Approximately one third of this wall remains to be formed and about two thirds require shotcrete.
- Drilling and tie back installation:
  - Whaler wall 'A' – a new drill rig was deployed to-day. This rig is attached to a modified excavator. It has the capability to reach over and drill from the road. The original rig cannot be used on this section of wall 'A' because there is insufficient room between the road and the edge of the cliff to support it. 29 out of 59 tie backs are now complete.

### Signs

- One additional advisory sign was installed to-day at the following location:
  - Southbound 280 before Highway 92
  - The sign is the same as those installed June 9 and reads: '1 Closed at Devil's Slide'; 'MONTARA HALF MOON BAY BUSINESSES OPEN.'