



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 14

Repair Work

Devil's Slide (post mile 39.14)

- Whaler (bracing) wall construction:
 - Whaler wall 'A' (upper level ocean side) – complete.
 - Whaler wall 'B' (lower level ocean side) – excavation work started to-day.
 - Whaler wall 'C' (lower level cliff side) – complete.
 - Whaler wall 'D' (upper level cliff side) – shotcrete work. Wall is approximately 70% complete.
- Drilling and tie back installation:
 - Whaler wall 'A' – drilling continued using the reach over rig.
 - Stressing tie back cables also took place.
 - Whaler wall 'C' – drilling continued to-day.

Public Information

- Caltrans provided a site visit to Devil's Slide and interview for KNEW Radio and the Pacifica Tribune to-day. Descriptions and explanations about the construction work and status of repairs were provided during the site tour which lasted for about one hour.
- Devil's Slide repair progress was presented to the Midcoast Community Council Meeting in Montara. The chair of the council provided the Department with 17 questions prior to the meeting and the majority of these were addressed during the presentation. In addition to an update on repair progress, Caltrans re-stated and emphasized the primary goal of opening Highway 1 to two way traffic as soon as possible and in a safe manner. A public and council member question and answer session followed the presentation.