



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 22

Repair Work

Devil's Slide (post mile 39.14)

- Whaler wall 'A' (upper level ocean side) – drilling with reach over rig continued. 52 of 59 tie backs now installed. Tie back stressing continues.



Reach over rig drilling at wall A

- Whaler wall 'B' (lower level ocean side) – Excavation work continues.




Excavating a 'bench' for the drill rig at wall B

- Whaler wall 'C' (lower level cliff side) – drilling continued. 28 of 34 tie backs now installed.



Injecting grout for level C tie backs

- Compaction grouting continued behind wall A



Compaction grouting operation behind wall A