



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 24 and 25

Repair Work

Devil's Slide (post mile 39.14)

- Whaler wall 'A' (upper level ocean side) – drilling with reach over rig continued. 59 of 59 tie backs now installed. Tie back stressing continues.



Stressing wall A tie backs

- Whaler wall 'B' (lower level ocean side) – Drilling and shotcreting on different sections of wall B this weekend.



Drilling at wall B



Shotcreting wall B

- Whaler wall 'C' (lower level cliff side) – drilling continued. 34 of 34 tie backs now installed.



Drilling at wall C

- Compaction grouting continued behind wall A.



Loading mixer to prepare grout