



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi




Daily Update
June 26

Repair Work

Devil's Slide (post mile 39.14)

- Whaler wall 'A' (upper level ocean side) – 59 of 59 tie backs now installed. 49 of 59 tie backs stressed.



Stressing wall A tie backs

- Whaler wall 'B' (lower level ocean side) – Drilling for tie backs continues. 4 of 58 installed. Excavating a 'bench' to create a work area continued.



Drilling at wall B



Excavating a bench at level B

- Whaler wall 'C' (lower level cliff side) – 34 of 34 tie backs now installed. Grouting of tie backs took place today.



Grouting tie backs at wall C

- Compaction grouting continued behind wall A.