



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi


Closed at Devils Slide
COAST IS CLEAR
BUSINESSES OPEN

Daily Update
July 11

Repair Work

Devil's Slide (post mile 39.14)

- Waler wall construction and tie back installation summary.



- Level 'B' (lower level ocean side) – Drilling for tie backs continued using the reach over rig. 54 of 58 tie backs now installed. Tie back stressing also continued.



Level B drilling – view from below

- Level 'D' (upper level cliff side) – Drilling for tie backs continued today from the temporary bench. 25 of 33 now installed.



Level D drilling

Retaining (micropile) Wall

- Drilling and driving steel piles continued today. 40 of 99 now installed.



Drilling for micropiles

Rock Bolts Above The Road

- Drilling started today for the installation of 50 rock bolts above level D. These 15 feet long bolts will knit fractured rocks together reducing the risk rocks falls.



Starting drilling for rock bolts above level D