



# Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 1 and 2

## Repair Work


Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – Drilling for tie backs continued this weekend using two drill rigs. Cable stressing also started at this level.



Drilling – level B

- Level 'C' (lower level cliff side) – Cable stressing continued throughout the weekend.



Level 'C' – cable stressing

- Level 'D' (upper level cliff side) – Drilling continued over the weekend. The drill rig is supported on a platform to position it correctly for the upper level.



Level 'D' – Drilling

### Retaining (micropile) Wall

- Excavation started to prepare a bench area for construction work.



Excavating for a retaining wall at north end of site

