



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
July 22 and 23

Repair Work

Devil's Slide (post mile 39.14)

- The concrete cap for the micropile wall was completed over the weekend and the forms removed.




Removing forms from the micropile wall cap

- Work continued to prepare the road surface for new paving by leveling the sub grade.



Preparing the sub grade

- Electrical contractor St. Francis Electric**, installed conduits and foundations for the slide sensor system.



Installing foundation and conduits for sensor system

- Yerba Buena Construction** continued with erosion control work on the cliff above the road.
- Maggori Construction continued to restore wells and pumps for the dewatering system.

** Disadvantaged Business Enterprise (DBE)