



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
July 28

Repair Work

Devil's Slide (post mile 39.14)

- Excavation work continued to provide access for drilling into the cliff below the road for horizontal drains.
- Yerba Buena Construction continued with erosion control work.



Installing anchors for the erosion control fabric

- Walers C & D were sandblasted today in preparation for staining.



Sandblasting walers above the road

- Electrical contractor St. Francis Electric continued to work on the slide sensor system.



Part of the layout for slide sensor system

- Maggiora Bros. continued to perform restoration work on the pump and well system.



Planning with the pump / well contractor



Well restoration work

Slide Location No. 3 (post mile 39.77)

- Construction of the retaining wall at this location continued to day with H-beam installation.