



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
July 8 and 9

Repair Work

Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – Drilling for tie backs continued over the weekend using two rigs. At one point drillers encountered interference from a level A tie back. Appropriate corrections were made and drilling continued.
- Level 'D' (upper level cliff side) – Two rigs being used to drill tie backs over the weekend.

Retaining (micropile) Wall

- Drilling and driving steel piles continued throughout the weekend.

Information Signs

- On July 6 additional signs were installed at two locations – see below.



SB Rte 35 near SB Hwy 1



SB Rte 280 near SB Hwy 1