

APPENDIX C

PHOTOS TAKEN DURING THE FIELD WORK



Beginning of PES 1



End of PES 1



Pavement Condition within PES 1



Beginning of PES 2



Pavement Condition within PES 2



Beginning of PES 3



End of PES 2



Pavement Condition within PES 3 (Rut Measurement with a 6-ft Straight Edge)



End of PES 3



Pavement Condition within PES 4



Beginning of PES 4



End of PES 4



Beginning of PES 5



End of PES 5



Pavement Condition within PES 5 (Rut Measurement with a 6-ft Straight Edge)