STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
Form HC-10A4 (Rev. 7/85)

04-0120F4
04-SF-80-13.2,13.9
SAS

Report No.	371
Page	1
Date	12/19/2007
Cont. Hrs.	None
Insp. Hrs.	0600-1430

ASSISTANT STRUCTURE REP.'S DAILY REPORT

Location & Description of Operation	SAS - TEMPORARY TOWERS

Falsework Review

EQUIPMENT AND/OR LABOR:

EQPT. NO.	NO. Personnel	DESCRIPTION (Equipment or Labor)	REGULAR	OT	DT	RENTAL			Idle or Down	WEATHER Pt. Cloudy / REMARKS
			HOURS - ITEM NO.							
Review plans and Specifications.										
Witnessed 1-Day compressive strength concrete cylinder breaks for Mix design 160061 at RMC facility in San Ramon.										
Mix # 1. with Adva-100, sample # 1 - 9.38 MPA and sample # 2 - 11.16 MPA.										
Mix # 2. with Adva-140, sample # 1 - 8.31 MPA and sample # 2 - 9.50 MPA.										
Helped SKYWAY with quantities.										

REC'D '07 DEC 2 2007 056

Signature

TE - C

Title

Arashdeep Pannu