STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
Form HC-10A4 (Rev. 7/85)

04-0120F4
04-SF-80-13.2,13.9
SAS

Report No.	373
Page	1
Date	12/21/2007
Cont. Hrs.	None
Insp. Hrs.	0600-1430

ASSISTANT STRUCTURE REP.'S DAILY REPORT

Location & Description of Operation	SAS - TEMPORARY TOWERS

Falsework Review

HOURS - ITEM NO.

EQUIPMENT AND/OR LABOR:

EQPT. NO.	NO. Personnel	DESCRIPTION (Equipment or Labor)	REGULAR	OT	DT	RENTAL			Idle or Down	WEATHER Clear / REMARKS
Review plans and Specifications.										
Witnessed 3-Day compressive strength concrete cylinder breaks for Mix design 160061 at RMC facility in San Ramon.										
Mix # 1. with Adva-100, sample # 1 - 38 MPA and sample # 2 - 45 MPA. (Sample taken on 12/18/07).										
Mix # 2. with Adva-140, sample # 1 - 38.5 MPA and sample # 2 - 41.8 MPA. (Sample taken on 12/18/07).										

REC'D '07 DEC 29 AM 10:54

Signature

TE-C

Title

Arashdeep Pannu