STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
Form HC-10A4 (Rev. 7/85)

04-0120F4
04-SF-80-13.2,13.9
SAS

Report No.	385/395
Page	1
Date	1/2/2008
Cont. Hrs	None
Insp. Hrs	0630-1500

ASSISTANT STRUCTURE REP.'S DAILY REPORT

Location & Description of Operation	SAS - TEMPORARY TOWERS

Falsework Review

EQUIPMENT AND/OR LABOR:

EQPT. NO.	# Personnel	DESCRIPTION (Equipment or Labor)	REGULAR	OT	DT	RENTAL			Idle or Down	WEATHER Clear / REMARKS
			HOURS - ITEM NO.							

Review plans and Specifications.

Witnessed 15-Day compressive strength concrete cylinder breaks for Mix design 160061 at RMC facility in San Ramon.

Mix # 1. with Adva-100, sample # 1 - 66.36 MPA and sample # 2 - 64.83 MPA. (Sample taken on 12/18/07).

Mix # 2. with Adva-140, sample # 1 - 65.85 MPA and sample # 2 - 66 MPA. (Sample taken on 12/18/07).

REC'D '08 JAN-12 #003167

Signature

TE-C
Title

Arashdeep Pannu