

ASSISTANT STRUCTURE REP.'S DAILY REPORT

Location & Description of Operation SAS - TEMPORARY TOWERS

Falsework Review

HOURS - ITEM NO.

EQPT. NO.	# Personnel	DESCRIPTION (Equipment or Labor)	REGULAR	OT	DT	RENTAL		Idle or Down	WEATHER
									SHOWERS/FOG
									REMARKS

Review plans and Specifications.

Bi-weekly Safety meeting.

Witnessed 28-Day compressive strength concrete cylinder breaks for Mix design 160061 at RMC facility in San Ramon.

Mix # 1. with Adva-100, sample # 1 - 65 MPA, sample # 2 - 64 MPA and sample # 3 - 65.7MPA (Sample taken on 12/13/07).

Mix # 2. with Adva-140, sample # 1 - 67 MPA, sample # 2 - 67 MPA and sample # 3 - 76 MPA (Sample taken on 12/13/07).

On my way back Jim D. (ABF) and Bob F. (CEMEX) called me if I could go back and witness 2 more breaks for Mix # 2. I informed Bob F. that it would be okay to break the remaining cylinders without me witnessing them. Asked Bob F. to fax me copy of the break strengths, to compare with the rest of the breaks.

Contractors weekly progress/schedule meeting.

REC'D *08 JAN-12 #003173

ABF
 Signature

TE - Civil
 Title
 Arashdeep Pannu