

Job Stamp
 04-0120F4
 SFOBB SAS

Const. Calendar Day No. 439
 Project Work Day No. 649
 Date 02/27/2008
 Shift Hours Start 0700 Stop 15:30
 Inspector Shift 6:30 AM to 3:00 PM

Assistant Structures Representative **CONTRACTOR - ABFJV**

EQUIPMENT AND/OR LABOR:			HOURS - ITEM NO.										IDLE OR DOWN	REMARKS		
Equip. #	NO. MEN	DESCRIPTION (Of Equipment or Labor)														Name
1																
2																
3																
4																
5																
6																
7																

I looked at some of the RFIs & SUBs that has been sent my way and have not seen anyone that pertain to the E2 cross beam, yet.

SAFETY

Aaron & I went out to Berth 7 today, the site of the 300 ton crane barge that is being assembled. This was the first day of assembling the base of this barge together. The only item of interest during this operation was a SAFETY issue that was addressed by Aaron at my presence. We witnessed that two ABF employees were directly working underneath the tubs that was in the air and attached to a crane. They were torquing bolts at the time we saw them. Aaron walked over to the superintendent/Foreman, Ed Myers and pointed out the potential hazard associated with their operation. Ed agreed with our assessment and called off his employees and pointed out that he would have them reach the bolts from the outside of the footprint of the tub. Please see attached photos

I am 98% done with the Concrete pour records on the E2/T1 project and archived 9 binders of documentations.

Moreover, read the Special Provisions on some of the relevant items to the E2 cap beam.

Inspector: 

Saman Soheili _____ Trans Engineer (D)/Asst. Struct. Rep _____

