

STATE OF CALIFORNIA	Job Stamp	7-day Const. Calendar	Day No. 427
DEPARTMENT OF TRANSPORTATION	SFOBB SAS	Project Work Day No.	Day No. 637
Form HC-10A (Rev. 6/80)	04-0120F4	Date	02/13/2008

Inspectors Hours	Start	0700	Stop	1530
Shift Hours	Start	0630	Stop	1500

ASSISTANT RESIDENT ENGINEER'S

CONTRACTOR – ABFJV

EQUIPMENT AND/OR LABOR:			HOURS - ITEM NO.										REMARKS				
Equ ip. #	NO. MEN	DESCRIPTION (Of Equipment or Labor)	48 - Bar Reinforcing Steel (Bridge)													Name	Contractor
		Regional Steel															
1	1	Superintendent	0													Gaige, Lance	RSC
2	1	Foreman	0													Van Brusselen, Jon	RSC
3	1	Ironworker	0													Jobe, Jason	RSC
4	1	Ironworker	0													Manzano, Jose	RSC
5	1	Ironworker	0													Lopez, Jorge	RSC
6	1	Ironworker	0													Greenlee, Tim	RSC
7	1	Ironworker	0													Rodriguez, Ernesto	RSC
8	1	Ironworker	0													Gomez, Daniel	RSC
9	1	Ironworker	0													Balderrama, Julio	RSC
10	1	Ironworker	0													Ortiz, Roberto	RSC
11	1	Ironworker	0													Mortenson, Kurt	RSC
12	1	Ironworker	0													Bell, Joe	RSC
13	1	Ironworker	0													Vasquez, Reynaldo	RSC
14	1	Ironworker	0													Stockton, Luke	RSC
15	1	Ironworker	0													Quiroz, Victor	RSC
16	1	Ironworker	0													Rapasmussen, John	RSC
17	1	Ironworker	0													Leon, Moises	RSC

Weather: Sunny, mild, wet ground, Hi 60 F Lo 46 F.

Description of Operation:

ABF

See L. Mathur's diary for labor, equipment and daily activities.

Daily for Regional Steel

RSC is not on site today.

Office Work


- Attended weekly Concrete Meeting with ABF. Informed Jim Davidson (including provided plan sheets) of missing rebar discussed with Brandon Bedwell yesterday.
- Wrote daily diaries.
- Continued working on concrete folders electronically for – concrete and gradation test results. Logged test results and filed electronic documents.
- Continued working Estimate 22 calculations.
- Check email and responded.
- Transported concrete cylinders cast 2/8/08 to Sacramento Lab, 5900 Folsom Blvd., Sacramento, CA.

NOTES:

- Informed Brandon Bedwell ABF about missing rebar described in yesterdays diary. 4-#25L14L21, 4-#25L15L21 and 1-#36L14T91.

Inspector:

Pamela Gagnier



Trans Engineer (C)/Asst. Struct. Rep