




- 12:15: All workers were mobilized back to the Traylor Dutra Conex box.
- See attached photos

- Reviewed open submittals and RFIs

**Inspector:**


Gina Rizzardo

A handwritten signature in blue ink, appearing to read "Gina Rizzardo", written over a horizontal line.


Transportation Engineer/Assistant Structure Rep.




281 SCF Moore Bros Torch



1. Torched through obstruction on one side.



2. Tried to break away obstruction by prodding it with long rod.



3. Used Vertical Drill to  
break off other end of  
obstruction.



3. Obstruction was  
identified as 1 1/4"  
Dewey Dag Rod, Gr. 75