

TOLL PROGRAM/DIST. 4 CONSTR.

Job Stamp:
04-SF-80-13.2/13.9 04-0120F4
SFOBB SAS
San Francisco Co. in San Francisco
Fm 0.6 km to 1.3 km East of Yerba Buena
Tunnel East Portal

Report No. 7-day const. cal.: 709
Project work day: 919
Date the Shift Began: 11/21/08
 NIGHTWORK FRIDAY
Shift Hrs Start 7:00 Stop 15:30
Engineer's Hrs Start 7:00 Stop 15:30

46.B

ASSISTANT RESIDENT ENGINEER'S DAILY

BRIDGE

REPORT

Location: W2 Cap Beam	Weather: clear/cold
Remark: ironwork/cooling pipes/sandblast	Hi 63F/Lo 41F

Description of Operation:

		HOURS - ITEM NO.						CONTRACTORS		
ITEM NO. >>		38	48	133				Prime	American Bridge / Fluor JV	(P)
		Structural Concrete, Bridge	Bar Reinforcing Steel (Bridge)	Construction Surveying				Sub #1	Regional	(1)
EQUIPMENT AND/OR LABOR:								Sub #2		(2)
EQPT. NO.	NO. MEN	DESCRIPTION (Of Equipment or Labor)	RT	RT	RT			Sub #3		(3)
								Sub #4		(4)
								Sub #5		(5)
								REMARKS		Prime / Sub
								Name	Classification	

For ABF equipment/personnel hours, please see Lalit Mathur's diaries.

I made two attempts in the morning to go to the field but the traffic was backed up so I turned around just before the onramp, which was also backed up. Radio broadcasts said the metering lights were just red. I also found out that ABF had a half-day. They had a bbq planned for their staff & crews.

I read from the standard specifications all day.

Reports from Sacramento indicate that our cylinders broken at 9 days are achieving the specified 56-day design strength.

RECT-09 JAN-06 #008232

Materials:

Insp. Hrs.	
REG: 8.0	INTERMITTENT INSPECTION
OT:	


David Chung

TE/CT
Title

46.02