



**Caltrans**


**STATE OF CALIFORNIA  
DEPARTMENT OF TRANSPORTATION  
Contract 1020F - SFOBB - Superstructure  
Larry Gustafson**

**Tuesday May 19,2009: Observation from Engineer's boat between 1330 and 1430 - Clear,  
Cool and light breeze.**

- **E2 - West Elevation**



**E2 - South Elevation - some steel remains from soffit form**



REC'D '09 JUN-05 #009772

- GW - Pile driving complete - battered piles being cut off




GW & GE - View from West




- Temporary "F" Towers - no observed activity



- W2 - East Elevation from water level



- **E Line Temporary Truss - add on in progress**




**E Line - another view**



• Temporary Trusses at Pier 7



Another view



- Shearleg Crane being prepped for Temporary Truss lift



Shearleg Crane lifting harness




- **E2 West Elevation**



- **GW - Pile Sleeve Grouting**



- T1 Tower Foundation - View from East Line Temporary Truss - No observed activity



- Temporary Truss E Line



- East Line Temporary Truss - Pulling Cables



- West Line Temporary Truss - Grinding Cradle Pedestals




- W2 - Row of shores has been removed - continuing removing shoring braces




**W2 Shoring - Brace removal**



**W2 - Complete East Elevation**



**W2 - East Elevation - South Portion**




**W2 - East Elevation - North Portion**



**W2 - Setting Strand Jack @ South Elevation**



**W2 - Central South void at West Side**



**W2- West Elevation - North portion - Protective covers have been placed on Hinge "K" Macalloy rods**



**W2 - West Elevation - South (East Bound) portion - protective covers on Macalloy rods had been placed previously**



**W2 - Setting Stand Jacks at North (West Bound) area**



**W2 - Setting Strand Jacks at South (East Bound) area**



