

STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
Contract 1020F - SFOBB - SAS - Superstructure
Larry Gustafson - Senior Schedule
Week ending 24-Jul-2009

Tuesday July 21, 2009: Observation from Engineer's Boat between 1300 and 1400 -
Overcast, Cool & Light Breeze

- Shearleg Crane Unloading Temporary Trusses (G to H) & (H to Hinge A)



View of Shearleg Crane unloading Temporary Truss from "Zen Hua 18" ZPMC Ship



REC'D H31 AUG-31 #010913

Temporary Trusses that have been loaded onto barges



A view from Pier 7



- **Temporary Tower West Bound GWE - to left of East Bound GE Towers**



Man-basket in action



Another view of Temp Tower GWE from East



• **East Elevation of W2 with T1 Foundation in foreground**



- **Underside of E Line Temporary Truss - showing location of Lift Cradle**



Status of Temp Trusses



**Thursday July 23, 2009 : Observation from Yerba Buena Island between 0930 and 1100 -
Overcast, Cold & Windy**

- **Temporary Tower GWE - in center of between "W" Line & "E" Line**



Closer View of Tower GWE




- **OBG Cradle & Cradle Pusher on "E" Line Temporary Truss**



Prepping Pedestals for Cradle Bearing pads



Temporary Trusses being stored on barges North of work area



General Status View of Temporary Trusses



- **W2 - Work at West Bound Column Top**



W2- Collars at West Bound Column Bottom



W2 - Top Deck - North end Strandjacks




W2 - Strandjack at West edge



W2 - holes cut in soffit deck for lowering



Cut out hole layout



W2 - Working on deck lowering arrangement



W2 - East Elevation showing Strandjacks



W2 - East Elevation



W2 - East Elevation Southern portion



W2 - East Elevation Northern Portion

