

04-SF-80-13.2/13.9
04-0120F4
SFOBB - SAS

Report No 812 (7 Workday Calendar)

Date March 4, 2009

M T **W** T F S S Circle Day

Hours Start on Wk _____ to _____

Prime Contractor: ABF

COO 36 S1
REPORT

ASSISTANT RESIDENT ENGINEER'S DAILY T1 (1/4) Anchorage Mock Up on Pier 7 Yard

Location & Description of Operation Photo 1 - 3 show 2nd lift of concrete base pad. No work was done today due to heavy rain.

Reference: mock up procedure STEP # 4.

EQUIPMENT AND/OR LABOR			HOURS-ITEM NO.								WEATHER	
EQPT NO	NO OF MEN	DESCRIPTION OF EQUIPMENT OR LABOR									REMARKS Reason for Idleness or other remarks	
		Everadeo Hernandez (Laborer Foreman)										Rain Temp: 58°F
		Froylan Ruiz (Laborer)										
		Daniel Schwartz (Laborer Apprentice)										
2381		Diesel AC Generator Denyo MQ Power										

Katherine Quillin: ABF Field Engineer
Andre Markarian: ABF Office Engineer
ABF-CAL-TRN-001947 (T1 - Anchorage Grout Mock up Procedure)

REC'D H31 AUG 31 #010921


Michelle Chui, PE

ARE
Title *MAP*




Photo 1
4-Mar-09
T1 (1/4) Anchorage Mock Up
on Pier 7 Yard




Photo 2
4-Mar-09
T1 (1/4) Anchorage Mock Up
on Pier 7 Yard




Photo 3
4-Mar-09
T1 (1/4) Anchorage Mock Up
on Pier 7 Yard