



## Description of Work by ABF and its Sub-contractors.

### ABF

- All work is for the Temporary Towers and preparation for OBG.
- Howard is working on Elevator.
- Others are assisting with miscellaneous tasks at Pier 7.

### SDI

- SDI come in today continued working with grease caps.

METS inspector was suppose to come today to continue checking the top grease caps but did not come.

### Additional Work at or outside of W2 site:

- CC Myers have dismantled all of the existing side lined bridge.
- They have removed the crane from there.
- Reorganize and clean up at office to sort out W2 paper work.
- Revise the OBG and Crossbeam installation checklist few times.
- Organize the work for OBG.
- Continue working on checklist for OBG installation.
- Multitude of revisions on the list.
- Discussed the final list to Tai for 1E and 2E.
- Sorted out punch list.
- Prepared Visual Inspection Check List. Discussed with Gil and tai Lin.
- Attended Safety Meeting at 8 AM followed by Gary Pursell's Staff Meeting.
- The ship from China is expected to arrive on the night of Jan 19<sup>th</sup>.
- Attended a presentation at 1 PM -2:30 PM by Aaron Prachik about Punch List Items.
- Matt is working on establishing survey points from E2 to W2.



Inspector: Lalit Mathur, P.E.

\_\_\_\_\_  
Transportation Engineer (D)

## Visual Inspection Check List

Lift \_\_\_\_\_ Checked By \_\_\_\_\_ Date \_\_\_\_\_

	Out Side	Dents	Connections	Welds	Bolts	Paint
1	Top Deck					
2	Bottom					
3	Long Sloping Side, South					
4	Short Sloping Side, South					
5	Long Sloping Side, North					
6	Short Sloping Side, North					
7	West Side Stiffeners (1 E and 1W only)					
8	Cross Beam Connection to OBG					
	a. Top Side					
	b. Bottom Side					
	c. East Side					
	d. West Side					
9	Panel Points	South				
	a. PP					
	b. PP					
	c. PP					
	d. PP					
10	Panel Points	North				
	a. PP					
	b. PP					
	c. PP					
	d. PP					

## Visual Inspection Check List

Lift \_\_\_\_\_ Checked By \_\_\_\_\_ Date \_\_\_\_\_

	In Side	Dents	Connections	Welds	Bolts	Paint
11	Top Deck					
12	Bottom					
13	Long Sloping Side, South					
14	Short Sloping Side, South					
15	Long Sloping Side, North					
16	Short Sloping Side, North					
17	West Side Longitudinal PT Pipes (1E and 1W only) 86 each					
18	Rib Beam Connection to OBG					
	a. Top Side					
	b. Bottom Side					
	c. South Side					
	d. North Side					
19	Longitudinal Beams	South				
	a. Bracing					
	b. Top					
	c. Bottom					
20	Longitudinal Beams	North				
	a. Bracing					
	b. Top					
	c. Bottom					